



06/15/11

**Recommended Spare Parts**

**Model 600 UV SO<sub>2</sub> NDIR  
Gas Analyzer**

<b>Part Number</b>	<b>Description</b>
410291-3	Fuse, 2 Amp (Slo Blo) (230 VAC) (requires 2 fuses)
410289-1	Fuse, 4 Amp 250V (Slo Blo) (115 VAC)
311239-1	HC Nafion Dryer (Only required with Hydrocarbon Scrubber option)
310263-3	Pump, Sample
310309-5	Rebuild Kit, Sample Pump
410914-1	UV Lamp

	<b>If Optional CO<sub>2</sub> or O<sub>2</sub>:</b>
911003	Cell Assembly
ZZPZFP7-B050	Light Source / Chopper Assembly
ZZPZFP7-B030	O-Ring
310310-1	Sintered Metal Filter Rebuild Kit (O <sub>2</sub> only) (includes Filter Element, Springs, O-Ring)
ZZPZFP7-B070	Window